

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-010265**Date Inspected:** 06-Nov-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Chen Ying Xin**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Umesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

Bay 11 Strut Angle Plate

This QA inspector performed Ultrasonic Testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT reports for this date. The members are identified as Tower Components. The weld designations reviewed are as follows.

WD1-SA3-18-109M-1-1A/B

WD1-SA3-18-109M-2-1A/B

WD1-SA3-18-109M-3-1A/B

WD1-SA3-18-109M-4-1A/B

WD1-SA3-18-109M-5-1A/B

WD1-SA3-18-109M-6-1A/B

WD1-SA3-18-109M-7-1A/B

WD1-SA3-18-109M-8-1A/B

Bay 11 East Tower Lift 5

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 3 )

---

This QA inspector performed Ultrasonic Testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT reports for this date. The members are identified as Tower Components. The weld designations reviewed are as follows.

ESD1-TL5-2C/F-7A/B

WSD1-TL5-4C/F-8A/B

This Quality Assurance (QA) Inspector observed the following work in progress:

Bay 10

SMAW welding of weld joint 21 located on ND1-A6002-3.

Welder is identified as 056364. ZPMC CWI is identified as Mr. Chen Ying Xin.

The welding variables recorded by QC appeared to comply with WPS-B-T-2113.

SMAW welding of weld joint 27 located on ND1-A6002-15.

Welder is identified as 066443. ZPMC CWI is identified as Mr. Chen Ying Xin.

The welding variables recorded by QC appeared to comply with WPS-B-T-4113-1.

SMAW welding of weld joint 29 located on ND1-A6002-6.

Welder is identified as 066155. ZPMC QC is identified as Mr. Yu Zhi Lai.

The welding variables recorded by QC appeared to comply with WPS-B-T-4113-1.

SMAW welding of weld joint 28 located on ND1-A6002-2.

Welder is identified as 053049. ZPMC QC is identified as Mr. Yu Zhi Lai.

The welding variables recorded by QC appeared to comply with WPS-B-T-2113.

SAW welding of weld joint 1A/B(Repair) located on ND1-A5012-11.

Welder is identified as 0503060. ZPMC QC is identified as Mr. Yu Zhi Lai.

The welding variables recorded by QC appeared to comply with WPS-485-SAW-1G(2F)-FCM-REPAIR-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

### **Summary of Conversations:**

Only general conversation was held between QA and QC concerning this project.

### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod 134-8257-0045, who represents the Office of Structural Materials for your project.

---

## WELDING INSPECTION REPORT

( Continued Page 3 of 3 )

---

**Inspected By:** Gaikwad,Umesh

Quality Assurance Inspector

**Reviewed By:** Clifford,William

QA Reviewer